


St. Joseph School  
Bathrooms  
September 2011



Urinal in Boys Restroom. Deteriorated patch job traps odors and therefore emits a constant unpleasant smell.



Another Urinal in Boys Restroom. Crack in the urinal is another source of trapped odors. Floor patch indicates frequent problems with plumbing below the floor.